



INNOVATIVE IDEAS
EXCEPTIONAL DESIGN
UNMATCHED CLIENT SERVICE

Greater South Haven Drainage Study-
Coventry, New South Haven and Salt Creek Valley Commons
Porter County, Indiana

APPENDIX III B- Select Video Inspection Photographs



Picture 1 - Pipe 1010-1000: Deformed



Picture 2 - Pipe 2010-2005: Broken and Deformed



Picture 3 - Pipe 2010-2005: Top Fractured



Picture 4 - Pipe 2010-2020: Utility Perforation



Picture 5 - Pipe 3050-3040: Utility Perforation



Picture 6 - Pipe 4040-4050: Bottom Corroded Away



Picture 7 - Pipe 4040-4050: Deformed



Picture 8 - Pipe 4400-4300: Broken Bottom



Picture 9 - Pipe 4400-4300: Broken Bottom



Picture 10 - Pipe 6010-6000: Deformed



Picture 11 - Pipe 8010-8030: Deformed



Picture 12 - Pipe 8010-8030: Tap Root



Picture 13 - Pipe 8010-8030: Broken with Roots



Picture 14 - Pipe 8030-8010: Broken Bottom



Picture 15 - Pipe 8060-8050: Standing Water / Low Area



Picture 16 - Pipe 8400-8500: Corrosion, Poor Slope, Deposits