



INNOVATIVE IDEAS  
EXCEPTIONAL DESIGN  
UNMATCHED CLIENT SERVICE

Greater South Haven Drainage Study-  
Coventry, New South Haven and Salt Creek Valley Commons  
Porter County, Indiana

## APPENDIX IV B - Select Video Inspection Photographs



Picture 1 - Pipe 1100-1102: Debris



Picture 2 - Pipe 1100-1110: Bottom Corrosion



Picture 3 - Pipe 1110-1120: Blind Tap



Picture 4 - Pipe 1110-1120: Landscape Block



Picture 5 - Pipe 2040-2030: Deposits



Picture 6 - Pipe 2040-2041: Hardened Deposits



Picture 7 - Pipe 2040-2042: Deposits



Picture 8 - Pipe 2110-2100: No Structure at Transition



Picture 9 - Pipe 2191-2190: Deposits



Picture 10 - Pipe 2220-2200: Infiltration Deposits



Picture 11 - Pipe 2220-2200: Concrete Block



Picture 12 - Pipe 2221-2222: Deposits too Deep For Camera



Picture 13 - Pipe 2251-2253: Deposits



Picture 14 - Pipe 3020-3010: Large Rocks, Video Abandoned



Picture 15 - Pipe 3030-3035: Blind Tap



Picture 16 - Pipe 4030-4010: Deep Deposits



Picture 17 - Pipe 5010-5000: Deformed and Fractured